

### State of Utah

#### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

June 29, 2016

Richard S. Parkins, General Manager Fossil Rock Resources, LLC 225 North 5<sup>th</sup> Street, Suite 900 Grand Junction, Colorado 81501

Subject: 2015 Annual Report Review Completion, Fossil Rock Mine, C/015/0009, Task ID

#5077

Dear Mr. Parkins:

The Division staff has completed the review of the 2015 Annual Report. Enclosed is a copy of the review with each reviewer's comments.

Thank you for your diligence in completing the Annual Report. If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron R. Haddock Coal Program Manager

DRH/sqs
Enclosure
O:\015009.FR\WG5077 ANNUAL REPORT\ReviewCompletionLetter.doc



Haddock

Print Form	Submit by Email	Reset Form

# **Annual Report**

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by the date specified in the cover letter. During a complete inspection an inspector will check and verify the information.

GENERAL IN	FORMATION						
Company Nam	Fossil Rock Resources, LLC			Mine Name	Fossil Rock		
Permit Number	C/015/0009	C/015/0009			2020-02-21		
Operator Name	Fossil Rock Resou	Fossil Rock Resources/Canyon Fuel Company, LLC			+1 (435) 286-4880		
Mailing Addres	597 South SR24	597 South SR24			vmiller@bowieresources.com		
City							
State	Utah	Zip Code 84654					
				DOGM File Locati	ion or Annual Report Location		
Exces	s Spoil Piles	☐ Required ☐ Not Required					
				4th Quarter Inspections submitted to DOGM on January 4, 2016. purchased by Fossil Rock from PacifiCorp in June 2015. See note.			
Impo				3rd & 4th Quarter Inspections submitted to DOGM on January 4, 2016. Mine purchased by Fossil Rock from PacifiCorp in June 2015. See note.			
Other:							
OPERATOR COMMENTS							
1st and 2nd Quarter Inspections are assumed to be on file with DOGM having been submitted by PacifiCorp.							
REVIEWER COMM	MENTS	Met Requirements	$\boxtimes$	Did Not meet Requireme	nts		

The Fossil Rock mine was transferred from Trail Mountain to Fossil Rock Resources in 10/8/15. The Permittee submitted an application to add the old Cottonwood/Wilberg waste rock site to the Fossil Rock Mine (task #4790) and was approved on 5-20-15 by the Division. The waste rock pile inspections and PE certification are required for the 2015 Annual Report. The current owner of the Mine, Canyon Fuel Company, completed the third and fourth quarter refuse and pond inspections. The first pond and refuse inspection was completed by PacificCorp on 3/12/15. The total site storage capacity of the site is 784,000 cubic yards (36% of capacity). Trail Mountain ceased operations and will no longer haul material to the site. Vicky Miller, a employee of Canyon Fuel, completed the third and fourth quarter inspections on 9/16/15 and 12/9/15 and found both the pond and refuse pile to be in a stable condition. The waste rock site did not receive any fill and remained at 36% of total capacity. The pond was dry for the September inspection and only had one foot of water

ittee will submit a co	py to the Division fo	r record keeping.	ne second quarte . (CP)	er pond and refus	e inspection repor	ts on files and t

•

#### **COMMITMENTS AND CONDITIONS**

The Permittee is responsible for ensuring annual technical commitments in the Mining and Reclamation Plan and conditions accepted with the permit are completed throughout the year. The Division has identified these commitments below and has provided space for you to report what you have done during the past year for each commitment. If additional written response is required, it should be filed as an attachment to this report.

Title: REMINING WAST Objective: Provide an a Frequency: Annually Status: Ongoing Reports: Annual Repor Citation: MRP, R645-30	as-bu ts	ilt drawing of the work, ind	cluding soil	salv	age volumes
The re-mining project was	not sta	rted during 2015, therefore this	s requirement	is no	t fulfilled in the 2015 annual report.
Reviewer Comments	$\boxtimes$	Met Requirements			Did Not Meet Requirements
Inspection reports confirm	no act	vity at the site. PWB reviewed	2/8/2016.		
add the old Cottonwood/W	/ilberg	red from Trail Mountain to Foss waste rock site to the Fossil Ro ons and PE certification are requ	ck Mine (task #	4790	n 10/8/15. The Permittee submitted an application to 0) and was approved on 5-20-15 by the Division. The Annual Report. (CP)
The state of the s					
subsidence Frequency: Annually Status: Ongoing Reports: Annual Report	hotog ts				elicopter reconnaissance flights to monitor
Mining has not occurred at 2015.	this sit	e since the mine's temporary co	essation in 200	1, th	erefore subsidence monitoring was not necessary in
Reviewer Comments	$\boxtimes$	Met Requirements			Did Not Meet Requirements
The 2006 Annual report con	ıclude	d that subsidence monitoring re	eview of Area	24 ha	nd reached maximum defamation many years ago

The 2006 Annual report concluded that subsidence monitoring review of Area 24 had reached maximum defamation many years ago and that no future settling was occurring. Monitoring areas relative to the Mine were removed from reporting as of 2010, when subsidence had been demonstrated complete. The 2012 Annual Subsidence Monitoring report and the 2014 Annual Subsidence monitoring report monitored areas 23 and 24 as these two areas achieved 104% and 93% of the predicted maximum amount of settling, based on the National Coal Board predication model (See page 11 of the 2014 Annual Subsidence Monitoring Report). No subsidence

monitoring was required or submitted at this point in time. (CP)	

#### **FUTURE COMMITMENTS AND CONDITIONS**

The following commitments are not required for the current annual report year, but will be required by the permittee in the future as indicated by the "status" field. These commitments are included for information only, and do not currently require action. If you feel that the commitment is no longer relevant or needs to be revised, please contact the Division.

Title: Vegetation Monitoring Objective: Observe revegetation efforts Frequency: Annually upon revegetation Status: Revegetation efforts have not been initiated Reports: Annual Reports Citation: MRP, R645-301-231.100	
Title: Roof and Floor Samples Objective: To determine if toxic or acid forming potential exists Frequency: Annually during mining operations Status: To be initiated if mining resumes Reports: Annual Reports Citation: MRP Vol 1 Chapt 6 Section 6.6.5 pg 6-8	
Title: Groundwater Monitoring  Objective: Analyze mine working water balance, account for mine storage  Frequency: Annually during mining operations  Status: To be initiated if mining resumes  Reports: Annual Reports  Citation: MRP Vol 1 Chapt 6 Section 6.7 pg 6-10	e inflows, outflows, consumptive uses, and sump
Operator Comments	
Reviewer Comments	Did Not Meet Requirements

## **REPORTING OF OTHER TECHNICAL DATA**

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:	
Raptor Survey sent as separate file, no archaeological reports for 2015.	
Reviewer Comments	
Raptor survey reviewed and approved. Nice work. Please note locations of new and active Golden Eagle nests. If n protection measures should be reviewed to ensure protection is adequate. LR, 2/10/2016.	nining is to resume,

### **MAPS**

Copies of mine maps, current and up-to-date, are to be provided to the Division as an attachment to this report in accordance with the requirements of R645-301-525.240. The map copies shall be made in accordance with 30 CFR 75.1200 as required by MSHA. Mine maps are not considered confidential.

		Incl	uded	Confidential				
Map Name	Map Number	Yes	No	Yes	No			
Mine Map With Five Year Projected Plan			$\boxtimes$					
Reviewer Comments   Met Requirements  Did Not Mee			et Requirer	ments				
Mining via longwall methods was completed at the Mine in 2001. The Mine was sealed in April 2011. No mine map was submitted or required at the time of the 2015 Annual Report. No waste was placed at the site for the 2015 year and remaining activities did not commence in 2015.								